Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Construction of Gym and Yoga building at sundar nagara and mineral water unit in ward No.17
2	Administration Approval & Date	EE/RRND/AS/133/2015-16 Dtd.04-11-2015 by EE RRND
3	Technical Sanction Estimate No.& Date	CE/RRN/TS/199/2015-16 dated: 07.11.2015
4	Estimate Amount	Rs.125.00 lakhs
5	Job Code No.	017-15-000035
6	P-Code	P-3089
7	Agreement No & date	EE/RRND/AG No./152/2015-16 Dtd.15-03-2016
8	[illegible] Number & Date	EE/RRND/Wo No./138/2015-16 Dtd.15-03-2016
9	Contract Amount as per Agreement	Rs.1,09,79,183/-
10	Bill Amount	Rs.93,89,220/- 1st & Part bill
11	S.B.R. No. & Date	36/2017-18 Dtd:23-10-2017
12	Agency	V.Vishwanath
13	M.B. Number & Page No. of Measurement recordes	5709/ Pages.570801 to 570849/1
14	Date of Inspection	25-10-2017
15	[illegible]usures	1) 32 Number of photos taken during inspection
16	Inspection Report	The above site location has been Inspected by me along with the Concerned person, as per EE(RRN) Letter No EE/RRN/PR/548/17-18 Dated 25-10-2017. The measurements of the Items indicated in the MB, which are susceptible for measurments have been checked and found to be satisfactory

EE RR Nagara Division

25/10/2017
(R.Sathyanarayana)
Inspection Report officer,
R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner